MISSED APPROACH WITH COMMUNICATIONS FAILURE PROCEDURES

ELEV 319 FT

BALDONNEL / CASEMENT (MIL)

Instrument	Missed Approach with Communications Failure
Approach Procedure	
ILS y ILS z RWY 10 VOR / DME RWY 10 VOR / DME RWY 22 VOR / DME RWY 28 SRA RWY 10	Squawk 7600. Carry out missed approach as per procedure. Passing 13D outbound on R-232 BAL climb to 4000'. Passing 17D BAL climb 5000'. At 5000' route to DONEB and carry out one hold. Self-position for or approach to the appropriate runway at Dublin Airport